

Kit Number	Start Date	Start Time	End Date	End Time	Temperature	Facility	Room	Floor	Result	Variance	Analysis Date	%Moisture
9495483	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	MAIN OFFICE	1	0.8	0.5	2020-11-16	3.7
9495484	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	OFFICE MANAGER	1	< 0.3	0.5	2020-11-16	4.5
9495485	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	OFFICE MANAGER	1	< 0.3	0.5	2020-11-16	4.4
9495486	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	PRINCIPAL	1	0.9	0.5	2020-11-16	4.4
9495487	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	HEALTH ROOM	1	< 0.3	0.5	2020-11-16	3.6
9495488	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	ASSISTANT PRINCIPAL	1	< 0.3	0.6	2020-11-16	3.6
9495489	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	WORK ROOM	1	< 0.3	0.6	2020-11-16	4.5
9495490	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	NURSE	1	< 0.3	0.5	2020-11-16	4.5
9495491	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	CONFERENCE ROOM	1	< 0.3	0.5	2020-11-16	3.7
9495492	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	COUNSELOR OFFICE	1	0.6	0.5	2020-11-16	4.5
9495493	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	OFFICE 1	1	< 0.3	0.6	2020-11-16	4.4
9495494	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	OFFICE 2	1	0.8	0.5	2020-11-16	3.6
9495495	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	E1	1	< 0.3	0.5	2020-11-16	3.6
9495496	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	FAN	1	0.6	0.4	2020-11-16	4.5
9495497	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	E2	1	< 0.3	0.6	2020-11-16	4.5
9495498	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	E3	1	< 0.3	0.6	2020-11-16	3.7
9495499	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	F3	1	< 0.3	0.4	2020-11-16	4.5
9495500	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	F3	1	< 0.3	0.6	2020-11-16	3.7
9495601	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	GIRLS LOCKER ROOM	1	< 0.3	0.5	2020-11-16	4.5
9495602	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	BOYS LOCKER ROOM	1	< 0.3	0.4	2020-11-16	4.5
9495603	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	B WORK ROOM	1	< 0.3	0.6	2020-11-16	4.5
9495604	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	B1	1	< 0.3	0.5	2020-11-16	4.5
9495605	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	B2	1	< 0.3	0.5	2020-11-16	4.5
9495606	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	B2	1	< 0.3	0.6	2020-11-16	3.6
9495607	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	B3	1	< 0.3	0.5	2020-11-16	3.7
9495608	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	B4	1	< 0.3	0.5	2020-11-16	4.5
9495609	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	B5	1	< 0.3	0.5	2020-11-16	3.7
9495610	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	B6	1	< 0.3	0.5	2020-11-16	3.7
9495611	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	B7	1	< 0.3	0.6	2020-11-16	4.5
9495612	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	B7	1	< 0.3	0.6	2020-11-16	3.7
9495613	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	B8	1	0.7	0.4	2020-11-16	4.4
9495614	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	C1	1	< 0.3	0.5	2020-11-16	3.6
9495615	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	C2	1	< 0.3	0.4	2020-11-16	3.6
9495616	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	C3	1	< 0.3	0.4	2020-11-16	3.7
9495618	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	WORK ROOM	1	< 0.3	0.4	2020-11-16	4.5
9495622	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	C8	1	< 0.3	0.5	2020-11-16	4.4
9495623	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	C9	1	< 0.3	0.5	2020-11-16	5.2
9495624	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	C10	1	< 0.3	0.5	2020-11-16	4.5
9495625	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	C11	1	< 0.3	0.6	2020-11-16	4.5
9495626	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	C12	1	< 0.3	0.5	2020-11-16	4.5
9495627	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	C13	1	< 0.3	0.6	2020-11-16	3.6
9495628	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	D1	1	0.6	0.5	2020-11-16	2.9
9495629	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	D2	1	< 0.3	0.6	2020-11-16	4.4
9495630	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	D3	1	< 0.3	0.6	2020-11-16	4.4
9495631	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	D3	1	< 0.3	0.6	2020-11-16	3.6
9495632	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	D4	1	0.6	0.4	2020-11-16	5.3
9495633	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	D5	1	0.7	0.4	2020-11-16	5.3
9495634	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	D6	1	0.8	0.5	2020-11-16	4.5
9495635	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	G1	1	< 0.3	0.4	2020-11-16	4.4
9495636	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	G2	1	0.9	0.4	2020-11-16	5.2
9495637	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	G3	1	1	0.5	2020-11-16	4.4
9495638	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	G4	1	0.8	0.5	2020-11-16	4.4
9495639	2020-11-08	10:00 am	2020-11-10	3:00 pm	62	PILOT BUTTE MS	G5	1	< 0.3	0.6	2020-11-16	4.5