

Kit Number	Start Date	Start Time	End Date	End Time	Temperature	Facility	Room	Floor	Result	Variance	Analysis Date	%Moisture
9495466	2020-11-03	7:00 am	2020-11-05	7:00 am	62	BEND TRANSPORTATION	RECEPTIONIST	1	< 0.3	0.4	2020-11-09	5.3
9495467	2020-11-03	7:00 am	2020-11-05	7:00 am	62	BEND TRANSPORTATION	ASST DIRECTOR	1	< 0.3	0.4	2020-11-09	4.5
9495468	2020-11-03	7:00 am	2020-11-05	7:00 am	62	BEND TRANSPORTATION	OFC MANAGER	1	< 0.3	0.4	2020-11-09	4.5
9495469	2020-11-03	7:00 am	2020-11-05	7:00 am	62	BEND TRANSPORTATION	DIRECTOR	1	< 0.3	0.4	2020-11-09	4.5
9495470	2020-11-03	7:00 am	2020-11-05	7:00 am	62	BEND TRANSPORTATION	DIRECTOR	1	< 0.3	0.4	2020-11-09	4.5
9495471	2020-11-03	7:00 am	2020-11-05	7:00 am	62	BEND TRANSPORTATION	CONFERENCE ROOM	1	< 0.3	0.4	2020-11-09	4.5
9495472	2020-11-03	7:00 am	2020-11-05	7:00 am	62	BEND TRANSPORTATION	TRAINING OFC	1	< 0.3	0.4	2020-11-09	4.5
9495473	2020-11-03	7:00 am	2020-11-05	7:00 am	62	BEND TRANSPORTATION	TRAINING OFC	1	< 0.3	0.3	2020-11-09	5.3
9495474	2020-11-03	7:00 am	2020-11-05	7:00 am	62	BEND TRANSPORTATION	TRAINING ROOM	1	< 0.3	0.3	2020-11-09	5.3
9495475	2020-11-03	7:00 am	2020-11-05	7:00 am	62	BEND TRANSPORTATION	TRAINING ROOM	1	< 0.3	0.4	2020-11-09	4.5
9495476	2020-11-03	7:00 am	2020-11-05	7:00 am	62	BEND TRANSPORTATION	TRAINING ROOM	1	< 0.3	0.4	2020-11-09	4.5
9495477	2020-11-03	7:00 am	2020-11-05	7:00 am	62	BEND TRANSPORTATION	DISPATCH	1	< 0.3	0.4	2020-11-09	5.3
9495478	2020-11-03	7:00 am	2020-11-05	7:00 am	62	BEND TRANSPORTATION	SHOP OFC 1	1	< 0.3	0.3	2020-11-09	5.2
9495479	2020-11-03	7:00 am	2020-11-05	7:00 am	62	BEND TRANSPORTATION	SHOP OFC 1	1	< 0.3	0.4	2020-11-09	4.5
9495480	2020-11-03	7:00 am	2020-11-05	7:00 am	62	BEND TRANSPORTATION	SHOP OFC 2	1	< 0.3	0.4	2020-11-09	4.5
9495481	2020-11-03	7:00 am	2020-11-05	7:00 am	62	BEND TRANSPORTATION	BREAKROOM	1	< 0.3	0.4	2020-11-09	3.7
9495482	2020-11-03	7:00 am	2020-11-05	7:00 am	62	BEND TRANSPORTATION	BREAKROOM	1	< 0.3	0.4	2020-11-09	4.5