

Radon test result report for:**ACE**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
7197458	1	2018-01-16 @ 7:00 am	2018-01-18 @ 8:00 am	< 0.3	2018-01-19
7197459	2	2018-01-16 @ 7:00 am	2018-01-18 @ 8:00 am	< 0.3	2018-01-19
7197460	3	2018-01-16 @ 7:00 am	2018-01-18 @ 8:00 am	0.9 ± 0.2	2018-01-19
7197461	4	2018-01-16 @ 7:00 am	2018-01-18 @ 8:00 am	0.6 ± 0.2	2018-01-19
7197462	5	2018-01-16 @ 7:00 am	2018-01-18 @ 8:00 am	< 0.3	2018-01-19
7197463	6	2018-01-16 @ 7:00 am	2018-01-18 @ 8:00 am	0.8 ± 0.2	2018-01-19
7197464	6	2018-01-16 @ 7:00 am	2018-01-18 @ 8:00 am	0.5 ± 0.2	2018-01-19
7197476	AV ROOM	2018-01-16 @ 7:00 am	2018-01-18 @ 8:00 am	< 0.3	2018-01-19
7197473	COUNSELOR	2018-01-16 @ 7:00 am	2018-01-18 @ 8:00 am	0.5 ± 0.2	2018-01-19
7197468	LIBRARY MOD	2018-01-16 @ 7:00 am	2018-01-18 @ 8:00 am	0.7 ± 0.2	2018-01-19
7197469	LIBRARY MOD	2018-01-16 @ 7:00 am	2018-01-18 @ 8:00 am	< 0.3	2018-01-19
7197467	MULTIPURPOSE	2018-01-16 @ 7:00 am	2018-01-18 @ 8:00 am	0.7 ± 0.2	2018-01-19
7197465	MULTIPURPOSE	2018-01-16 @ 7:00 am	2018-01-18 @ 8:00 am	< 0.3	2018-01-19
7197466	MULTIPURPOSE	2018-01-16 @ 7:00 am	2018-01-18 @ 8:00 am	0.9 ± 0.2	2018-01-19
7197471	OFFICE	2018-01-16 @ 7:00 am	2018-01-18 @ 8:00 am	0.7 ± 0.2	2018-01-19
7197472	PRINCIPAL	2018-01-16 @ 7:00 am	2018-01-18 @ 8:00 am	< 0.3	2018-01-19
7197470	PRINCIPAL	2018-01-16 @ 7:00 am	2018-01-18 @ 8:00 am	0.9 ± 0.2	2018-01-19
7197474	STAFF LOUNGE	2018-01-16 @ 7:00 am	2018-01-18 @ 8:00 am	< 0.3	2018-01-19