

## District Lead Testing Fixture Report Template

Dist ID:	School District Name:	Building Name:	Fixture Number	Location at Site	Date of Test	Test Results	Date of Retest
OR100031	Bend-LaPine Schools	Maintenance Facility	19768101-001SF	Building 1 Conference Room	4/20/23	ND	
OR100031	Bend-LaPine Schools	Maintenance Facility	19768102-001DW	Building 2 Main Hallway	4/20/23	ND	
OR100031	Bend-LaPine Schools	Maintenance Facility	19768103-001DW	Building 3 Main Hallway	4/20/23	ND	
OR100031	Bend-LaPine Schools	Maintenance Facility	19768103-002SF	Building 3 Staff Lounge	4/20/23	ND	
OR100031	Bend-LaPine Schools	Maintenance Facility	19768104-001SF	Building 4 Multipurpose Rm	4/20/23	ND	
OR100031	Bend-LaPine Schools	Maintenance Facility	19768104-002DW	Building 4 Main Hallway	4/20/23	1.1	